



BLADE BOLTS for LAZER Blades Part No. TX 32205K10

As fitted to Procut, Stealth and Pegasus series mowers.



SAFETY WARNING

It has been reported that a number of blade bolts from one production batch have failed with the head of the bolt retaining the Lazer blade breaking away from the shank. This allows the blade to be thrown and in a worst case situation, the discharged blade could cause severe injury to any person in the vicinity of the mower whilst operating.

ACTION REQUIRED

1. Assess all blade bolts to identify version. Check both spares stock and those fitted to machines. 'Older version' is suspect version. Latest version is recognized good stock.
2. Remove and return for warranty credit any older version blade bolts.

